

STATUS OF UNITS

Hull no. 1845


Week 15

12.04.2016

Unit no.	Cutting		Prefabrication				Coupling of units	
	plates	profiles	preass	panels	status		status	
	%	%	%	%	LCN	WELD	LCN	WELD
02 F	100	100	100	100	100	100	10	
03 E	100	100	100	100	100	100	55	30
04	100	100	100	100	100	100	70	40
05 D	100	100	100	100	100	100	40	20
06 E	100	100	100	100	100	100	15	
07 D	100	100	100	100	95	90		
100 D	100	100	100	⊗	100	100	90	75
101AFT F	95	100	100	100	55	45		
101FORE F	100	100	100	100	45	15		
102P E	100	100	100	100	100	100		
102S E	100	100	100	100	100	100		
103P J	100	100	100	100	100	100	60	30
103S J	100	100	100	100	100	100	60	30
104P H	100	100	100	100	100	100	70	40
104S H	100	100	100	100	100	100	70	40
105P J	100	100	100	100	100	100	40	20
105S J	100	100	100	100	100	100	40	20
106P E	100	100	100	100	100	100	15	
106S E	100	100	100	100	100	100	15	
201P D SUP	95	95	80	50				
201S D SUP	95	95	80	50				
201 D INF	95	95	80	50				
202INF F	100	100	95	100	20	15		
202SUP F	100	100	95	100	100	100		
203 J	100	100	100	100	100	100		
204 D	100	100	100	100	100	95		
205 F	100	100	100	100	80	65		
206 G	100	100	100	100	85	80		
207 B	100	100	100	100	65	35		
300 B	95	90	100	100	95	95		
301 B	100	100	100	100	10	5		
302P B	100	100	100	100	50	30		
302S B	100	100	100	100	50	30		
303 C	100	100	85	10				
304 D	100	100	100	100	100	100		
305 D	100	100	100	100	75	55		
306 C	100	100	100	100	60	55		
307 B	100	100	100	100	50	30		
401 B	100	100	100	40				
404-AL C	100	80	70	30				
405 C	100	100	100	100	100	100		
504-AL								

Progress of project 845
Week 15, 2016.

Status of unit progress.



Pictures from erection platform











